



**Product Change Notice**  
e-disk<sup>®</sup> Altima<sup>™</sup> 2.5" PATA SSD  
New Firmware FL06  
PCN-MK-019-00  
July 16, 2013

**Overview**

Effective immediately, all e-disk<sup>®</sup> Altima<sup>™</sup> 2.5" PATA Solid State Drives will be shipping with a new firmware version FL06 replacing the current version FH06. The new firmware includes additional LED error codes on BIOS and bug fixes on IOC.

**Affected Products:**

All e-disk<sup>®</sup> Altima<sup>™</sup> 2.5" PATA Solid State Drives

**Recommendation:**

Firmware version FL06 is a recommended, but not mandatory upgrade to e-disk<sup>®</sup> Altima<sup>™</sup> 2.5" PATA Solid State Drives with firmware version FH06 or lower.

**Additional Information:**

Should you have any question, please do not hesitate to contact your BitMICRO Sales Representative at [sales@bitmicro.com](mailto:sales@bitmicro.com) or at 510-743-3100.